RG104 E-1 Box 183

# Mint of the United States at Philadelphia, Pa.,

COINER'S OFFICE,

Sept 27th, 1893.

Hon O. C. Bosbyshell.

Superintendent.

Sir.

I have the honor to state that the wood now furnished is not satisfactory, The supply is partly composed of green and decayed wood, which does not give the degree of heat expected and required for the Annealing furnaces, The contract calls for Oak Wood, one year seasoned, and this kind of wood is not delivered, — as maple and chestnut is found among the lots. Oak Wood is what is required, and I would thank you to have this matter remedied at once, as the want of the proper kind of wood, is detrimental to getting out the work.

I am

Very Respectfully Yours.

A. O. Heft

Coiner.

NARA RG104, Entry 1, Box 183

Mint of the United States at Philadelphia, Pa.,
Coiner's Office,
September 27, 1893

Hon. O.C. Bosbyshell.
Superintendent.

Sir.

I have the honor to state that the wood now furnished is not satisfactory. The supply is partly composed of green and decayed wood, which does not give the degree of heat expected and required for the Annealing furnaces. The contract calls for Oak Wood, one year seasoned, and this kind of wood is not delivered – as maple and chestnut is found among the lots. Oak wood is what is required, and I would thank you to have this matter remedied at once, as the want of the proper kind of wood, is detrimental to getting out the work.

I am,
Very Respectfully Yours,
W.S. Steel
Coiner.